

CONFIDENTIAL

1968 JAN 30 00 05Z

OUT 64200

1

P 292324Z JAN 68
FM NPIC WASHDC
TO AIG 7840
BT

C O N F I D E N T I A L CITE NPIC 2856.
CPIR:NPIC SER:F00592 UE MSN:314U 01JAN68H
DAY PHOTO. CAMERA ON 0355Z. OFF 0410Z. REF NPIC R-146/67
OCT 67 PAGE D-20. AMS SERIES L7014 SHEET 6249 IV.

PART I. SIGNIFICANT PHOTO INTERPRETATIONS**B. NEW TARGETS AND SIGNIFICANT CHANGES**

ITM01:NAM DINH TRANS SUBSTATION SGM:4XR4C CTY:VN 202200N1060812E
DES:THIS 110-KV TRANSFORMER SUBSTATION (SEE REF) IS INOPERATIVE.
APPROXIMATELY HALF OF THE CONTROL BUILDING IS COLLAPSED WITH NO
APPARENT ATTEMPT TO REPAIR OBSERVED, AND THE REMAINING PORTION
IS IN DISREPAIR. THE COVER HAS BEEN REMOVED FROM THE TRANSFORMER
SHELTER, THE TRANSFORMER OIL RESERVOIR TANK IS MISSING, AND
THE TRANSFORMER RADIATORS APPEAR DAMAGED. NO ELECTRICAL
EQUIPMENT IS OBSERVED WITHIN THE SUBSTATION AREA. A SMALL
DISTRIBUTION TRANSFORMER IS NOTED OUTSIDE OF THE EASTERN
PERIMETER OF THE SUBSTATION

25X1

PART II. OTHER PHOTO INTERPRETATIONS - NONE
GP-1

C O N F I D E N T I A L**END OF MESSAGE**

Declass Review by NGA

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	Cable Sec.	
	PP&B	
	Security	
	TSSG	
	PSG	
3,4	IEG	
5	IAS	
	DIAXX-4	
6	SRAD	
	[REDACTED]	
	DIA-AP	

25X1

CONFIDENTIAL

Advance Copy
Sanitized
With Text